

Conservation Area Appraisal

Oxenhope

# Station Road



This appraisal reviews the Oxenhope Station Road Conservation Area Assessment, which was published in November 2005. The Management Proposals included in this appraisal are based on the outcomes and priorities established by the local community during the public consultation process for the Conservation Area Assessment.

The next appraisal of Oxenhope Station Road Conservation Area will be undertaken by June 2014

**June 2009** 

City of Bradford MDC

## Conservation **Area Appraisal?**

## What is a What is a **Conservation** Area?

A Conservation Area Appraisal describes the character of a conservation area. It also describes the changes that have been happening to the conservation area. The appraisal finishes with management proposals which will help to conserve and enhance the area's special character and improve decision making.

The Government requires that all conservation areas have an upto-date appraisal. An up-to-date appraisal is one that has been undertaken in the last five years.

The following work has been done to deliver this conservation area appraisal:

- A photographic survey of the buildings in the conservation area
  - The assessment of the level of authenticity of most of the historic buildings
  - An assessment of the issues facing the conservation area at present
  - The survey and update of map data relating to the conservation area
- A review of the appropriateness of the conservation area boundary
  - An assessment as to whether new development has made a positive, negative or neutral impact on the character of the conservation area
    - The formulation of management proposals for the area

A conservation area is an 'area of special architectural or historic interest the character or appearance of which is desirable to preserve or enhance' (Section 69 of the Planning (Listed **Buildings and Conservation** Areas) Act 1990).

Oxenhope Station Road Conservation Area was originally designated in 1980. A review of the boundary was undertaken in 2005 and then adopted in November 2005.

Conservation area designation brings with it extra controls. These controls cover:

- demolition of buildings;
- minor developments such as extensions, satellite dishes and boundary walls; and
- works to trees.

The objective of these measures is to help preserve the special character and appearance of the area and maintain or improve its environmental quality. Whilst it is recognised that conservation areas must be allowed to evolve to meet changing demands it is important that this occurs within a framework of controlled and positive management.

## **Contents**

Background and Brief History3
Key Characteristics4
Strengths6
Weaknesses6
Opportunities7
Threats7
Conservation Area Maps8
Changes Affecting the
Conservation Area11
Negative Impacts13
Management Proposals14

## Contacts & Further nformation

**Design and Conservation Team** 

8th Floor, Jacobs Well, Manchester Road Bradford BD1 5RW

#### Telephone:

(01274) 434605

#### Fax:

(01274) 433767

conservation@bradford.gov.uk

#### Webpages:

www.bradford.gov.uk/conservation

www.bradford.gov.uk/ conservationassessments

### Listed Buildings:

www.bradford.gov.uk/listedbuildings



Oxenhope was one of the many medieval or post-medieval scattered settlements established in the Pennine uplands. Originally an outlying subordinate of Bradford Manor, there is no mention of Oxenhope Manor in the 1086 Domesday Survey and it was presumably one of the unnamed berewicks of Bradford. There are mentions of an area of land referred to as Hoxenehop, Oxop(e) and Oxenehope from 1191-3 onwards. The name Oxenhope literally means 'valley of oxen', from the Old English term hop meaning valley head and probably refers to the area's original use as summer grazing by cattle brought over from Bradford.

## **Pre 1086**

Oxenhope was originally an outlying part of Bradford Manor and was probably originally used for summer grazing by cattle brought over from Bradford with little by way of permanent inhabitation.

## **14th Century**

Permanent agricultural settlement occurred prior to the division of Haworth Township in the 14th century to form the new Townships of Near Oxenhope and Far Oxenhope. The latter contained Upper Town, Lower Town and Leeming.

## **16th Century**

A major impetus for the increase in the number of farms and therefore population in Oxenhope was the sale of all land owned by Eltoft, Lord of the Manor of Oxenhope between 1589 - 92. Then land was sold to a combination of sitting tenants and a small syndicate.

## 17th Century

By 1850 there were almost 20 textile mills of varying size in the area. Competition forced the smaller mills out of business while the larger

mills expanded and prospered further through the opening of the Keighley and Worth Valley Railway in 1867. The railway stimulated the expansion of Upper Town and Lower Town.

## **18th Century**

The building of small worsted mills and the construction of small cottages for textiles works in the area such as Shaw and Upper town marked the beginning of the areas industrialisation between 1792 and 1820.

## **19th Century**

Leeming Reservoir was constructed between 1872 - 78 to compensate the mill owners in the valley for the diversion of water to Bradford using conduits constructed across the moors.

## 20th Century

Oxenhope retained its industrial function until the latter half of the 20th century and despite later 'infill' developments, has the character and appearance of a group of distinct rural and industrial settlement.

# Key Characteristics

The following summarises the key elements of the character of Oxenhope **Station Road conservation area:** 

- 17th, 18th, and early 19th century buildings.
- Traditional natural building materials
- Road tightly enclosed by buildings and boundary walls
- A traditional roofscape
- Self contained sense of place
- A mixture of building types from detached properties to terraced rows
- Predominantly domestic, rural development and architecture

Right: Rose Bank still retains traditional sash windows and a four panelled door.

Below: Thorn Villa has retained several key characteristics including the boundary wall.

Below right: Traditional roof materials and full height chimneys.















Anti-clockwise from top right: The Barn on Harry Lane retains its original openings along with little alteration when converted to a dwelling.

Number 4, Eastville retains several traditional features.

Views out of Oxenhope from York Lane.

Number 9. Keighlev Road has a full set of traditional sash windows.

## **Summary of Important Features and Details**

Features and details contribute to the essential character of the conservation area:

- Original / traditional architectural detailing to houses reflecting past architectural styles.
- Terraced houses of high group
- Boundary walls to most buildings Stone street surfaces (where these remain in situ)
- Streets and lanes of varying lengths and irregular widths create views and vistas
- Formal building and boundary frontages on primary elevations
- Traditional roofscape of stone slate roofs and chimneys
- Survival of key open spaces and such as fields

## **Current Condition**

### **AUTHENTICITY 74%**

- Each historic building in a conservation area will have originally had features and details which contribute to the character of the conservation area.
- The level of authenticity is based on an assessment of each building to ascertain the level of retention of original features.
- Features assessed are: chimneys, roofs, rainwater goods, walls, windows and doors, boundary walls, porches, bargeboards, bay windows and shopfronts. Not all buildings will have all the above features and the scoring sheet is adjusted to take this into account.
- Only residential, commercial and civic buildings built prior to 1956 are scored.
- 78 properties were assessed for the purpose of the study; this is 85% of all properties within the conservation area.
- There are no listed buildings within Oxenhope Station Road Conservation Area



# Strengths

- A significant number of the buildings have retained many of their traditional features and details
- The street pattern has changed very little which is irregular and unique
- Significant areas of traditional streetscape materials are still in
- Key open spaces maintain their traditional character
- Traditional roofscape and skyline due to retention of chimneys and original roofing materials
- Traditional views and vistas have been maintained where the gaps between the houses that have not been in filled
- The large majority of the boundary walls are traditional
- Rural hamlet with definite sense of place
- The settlement has a distinctive and unique value
- Mature trees contribute to townscape
- Peaceful and secluded roads and avenues

A breakdown of the authenticity assessment shows which features and details in particular are being retained and/or maintained and where there are the greatest threats








- Inappropriate porches are detracting from the areas character
- Most traditional windows and doors have been lost
- Alteration and removal of chimneys is harming the skyline
- Inappropriate mortar, pointing, stonecleaning and clutter are undermining the group value of buildings
- Altered, replaced or removed boundary walls and bargeboards are harming the area's character and the group value of buildings

Opportunities

 Better decisions by all stakeholders (property owners, the Planning Service, Highways) through reference to the Conservation Area Assessment and this review and subsequent workshops and more communication with the Design and Conservation Team.



- The "Repair and Maintenance Guide" should help property owners make better informed decisions. This document is available on the Council's website at www.bradford.gov. uk/repairs.
- Enforcement action against unauthorised development and works to trees.
- Bringing vacant and underused buildings and sites back into full
- Redevelopment of buildings and sites currently detracting from the character and appearance of the conservation area



Poor maintenance of property

# **Threats**


- Continued removal of traditional features and details from buildings.
- Poor decisions concerning planning applications, enforcement cases, listed buildings, highway management, and trees.
- Development of key open spaces (including private gardens) and loss of mature trees
- Loss of historic street surfaces and traditional character of public realm.
- Continued vacancy and underuse of buildings and sites.



Signage that is not in keeping with the conservation area

## **Oxenhope Station Road Conservation Area**

## **Character Contributions and Key Views**






Conservation Area Boundary Areas providing a positive contribution to character Areas providing a *negative* contribution to character Areas providing a *neutral* contribution to character


NB The 'positive', 'negative' and 'neutral' areas relate to the contribution the site/building currently makes to the character of the Conservation Area. The classification in no way means that the site/building has no special architectural, historic or archaelogical interest.

## **Oxenhope Station Road Conservation Area**

## Listed and Key Unlisted Buildings, Open Spaces and Trees









NB This map does not identify key trees individually, but merely indicates where there is at least one important tree.

## **Oxenhope Station Road Conservation Area**

## **Land Use and Highway Materials**





Any changes that have had a significant impact on the character or appearance of the conservation area since the previous assessment in 2005 are detailed below.

# Changes affecting the Conservation **Area**

# **New Development**

25a Station Road has been granted permission in 2008 to extend the retail unit.

## **NEUTRAL CHANGE**

26 - 28 Station Road was granted permission in 2007 to convert the shop to two dwellings.

### **NEGATIVE CHANGE**

**LESSON**: While visually the conversion of the property has been The Manorlands was granted permission in 2006 for a change of use from a dwelling to a family support centre.

## **NEUTRAL CHANGE**

done with sympathy and could be classed as a neutral change the overall conversion has to be seen as a negative change as the original shops that where once located in the conservation area have now been lost and the setting and vibrancy of the area has been lost.





36 Station Road was granted permission in 2008 to convert the shop and first floor flat into a single dwelling.

## **NEGATIVE CHANGE**

**LESSON**: While visually the conversion of the property has been done with sympathy and could be classed as a neutral change the overall conversion has to be seen as a negative change as the original shops that where once located in the conservation area have now been lost and affect the setting and vibrancy of the area has been lost.

Thorn Lea was granted permission in 2007 to create car parking in front of the dwelling.

#### **NEGATIVE CHANGE**

**LESSON**: Decision makers should give greater consideration to the impact of their decisions on the character and appearance the conservation areas. The concrete surface is not desirable for a conservation area and a more appropriate material could have been used.

In 2007 Station House was granted permission to be demolished.

### **NEGATIVE CHANGE**

**LESSON**: The loss of Station House has a negative impact on the conservation area. Even though the building was built from different materials to the rest of conservation area it was still seen as an interesting building that had a relationship with the station nearby.

## Buildings

The no buildings that have become vacant since the publication of the Conservation Area Assessment

### **NEUTRAL CHANGE**

There is one building that still remains vacant since the publication of the Conservation Area Assessment:

B & S Motors Keighley Road

### **NEGATIVE CHANGE**

There are no buildings that have returned to use since the publication of the Conservation Area Assessment:

**NO CHANGE** 

# Works to Highways

There have been no major works to highways or replacement of street lighting or street furniture in the conservation area since 2005.

**NO CHANGE** 


## **Boundary**

The appropriateness of the **Oxenhope Station Road** conservation area boundary is deemed to be appropriate at present.

# Trees & Open Space

No trees of amenity or townscape value have been lost in the conservation area since the publication of the conservation area assessment.

## NO CHANGE/POSITIVE



# **Negative Impacts**

As part of the review of the conservation area a number of properties displaying inappropriate alterations and additions have been noted.

Whilst a minority are considered to have a severely negative impact on the character of the conservation area, there are a number of properties displaying relatively minor visual detractors, such as reduced or removed chimneys, inappropriate rainwater goods, inappropriately pointed elevations and modern windows and doors. The Council will look to ways of mitigating these works and will actively discourage the occurrence of similar situations arising within the conservation area in the future. Design guidance on the repair and maintenance of historic properties has recently been published and is available on the Council's website at www.bradford.gov.uk/repairs.



## **Management Proposals**

The overall aim of the Conservation Area Management Proposals is to preserve and enhance the character of the Conservation Area, by ensuring that the Council and the community work together to maintain historic features and details and limit the loss of character.

The objectives aim to:

- improve service delivery.
- raise awareness and understanding about the special character of the conservation area.
- improve decision making so that all repair, development and alteration result in a positive contribution to the character of the place.

The objectives of the Management Proposals are based on the issues identified in the Oxenhope and Leeming Conservation Area Assessment and prioritised by members of the community who took part in the Leeming Conservation Area Assessment public consultation.

	Objective	Actions	Timescale
1	Design and Conservation Team maintain contact with the local community	<ul> <li>Yearly newsletter about conservation</li> <li>Design and Conservation website to be made as informative, user friendly and up-to-date as possible</li> </ul>	Yearly 2009- 2014
2	Improved communication between Council Officers and key partners in the conservation area	<ul><li>Formation of a conservation area forum</li><li>Workshops</li></ul>	Monthly As required
3	Improve the quality and amenity value of the public realm, open spaces, highway materials and water courses in Oxenhope Station Road	<ul> <li>Closer working relationship between Design and Conservation and other Council Departments</li> <li>Production of design guidance for the enhancement of the public realm</li> </ul>	Continual  As resources permit
4	Maintain footpaths and boundary walls	Closer working between the Design and Conservation Team, property owners, Highways and the Rights of Way Team	Continual
5	Preserve and enhance features and details that contribute to the character of Oxenhope Station Road	Guidance for the repair and maintenance of historic buildings will be published by the Design and Conservation Team in 2007	Review guidance periodically
6	Promote good quality new development	<ul> <li>Production of guidance on appropriate sympathetic design to suit the character of the conservation area</li> <li>Production of design briefs were appropriate</li> </ul>	2009-2014 As resources permit
7	Ensure all investment is contributing to the character of the conservation area and its activities	Maintenance of links and discussions between     Design and Conservation Team and partners outside     of and within the Council	Continual
8	Monitor Planning Applications to add value to the historic environment	Design and Conservation Team to work more effectively within the wider planning service	Continual
9	Address illegal works to listed buildings and unauthorised development	Liaison between Design and Conservation Team and Planning Enforcement Team	Continual
10	Retain important trees	Liaison between Design and Conservation Team and Trees Team	Continual
11	Monitor Change loss/gain and feedback to local community and officers working in the conservation area	Design and Conservation Team to review Oxenhope Station Road Conservation Area every five years in line with Best Value indicators 219a, b and c	Review by May 2014

